0UT52J75

S E C R E T 292029Z

1953 037 29 22 07 2

25X1

1. CAMERA B 7 WAS USED IN MISSION 3760 FLOWN ON 26 OCTOBER 1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE.

A. THE EXPOSURE IS ADEQUATE. THE RESOLUTION IS GOOD BUT IS DEGRADED TOWARD OUTBOARD SIDE OF DATA CHAMBER EDGE OF THE FORMAT.

B. 9R SIDE: ALL PARTS OF THIS SIDE WERE SPOOLED WHILE Grace (File) DAMP. THERE ARE MANY PINHOLES THROUGHOUT THE MISSION. EXAMPLES OF THESE ARE IN FRAMES 008, 028, 033, 323, 542, 958, 1278 AND 1313. OUTBOARD EDGE STATIC WITH ASSOCIATED FOGGING IS PRESENT FROM FRAMES 000 TO 2029. MANUFACTURER SPLICES OCCUR THROUGH FRAMES 010 AND 1317 WITH ASSOCIATED CREASES, STREAKS, SCRATCHES, AND ABRASIONS. FOREIGN MATTER IS PRESENT INTERMITTENTLY IN/ON THE EMULSION THROUGHOUT THE MISSION. AN EXAMPLE OF THIS IS A FLY EMBEDDED IN FRAME 535.

C. 9L SIDE: INBOARD EDGE STATIC IS IN EVIDENCE IN THE FIRST 100 FRAMES OF THIS SIDE. MINUS DENSITY DOTS, 1.55"
APART AND 2.0" FROM THE OUTBOARD EDGE OCCUR PARALLEL TO THE

25X1

SECUE

GROUP 1
Excluded frem automatics
downstraining and
doctors trigging

Declassification Review by NGA/DoD

MAJOR AXIS OF THE FILM. PARTS 1, 4 AND 6 WERE SPOOLED WHILE DAMP. A MINUS DENSITY STREAK 0.1" FROM THE INBOARD EDGE IS PRESENT THROUGHOUT THE MISSION.

- D. BOTH SIDES: THE METERING IS SLIGHTLY ERRATIC AND THERE ARE MINOR PROCESSING STREAKS THROUGHOUT BOTH SIDES OF THE MISSION.
 THE LAST TITLED FRAME ON EACH SIDE IS 2829.
 - E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.
 - 3. POSITIVE:
 - A. THE PI SUITABILITY IS GOOD.
 - B. THE PRINTING AND PROCESSING OF THE POSITIVE WAS GOOD.
- C. CLOUDS DEGRADED OR OBSCURED 70 PER CENT OF THE MISSION.
 SECRET

-END OF MESSAGE-